




**Industry: Marine**  
**Part: Cylinder Head**

**0026**



Cylinder



Dye Check



Through Crack




Grinding to Fit Patch



New Patch




Fitting of Patch




Fitting of Patch




Dye Check




Stitching Repairs in Progress




Stitching Repairs in Progress



Stitching Repairs in Progress



Installation of Patch




Stitching of Patch



Stitching of Patch



Stitching using Right Angle Tooling



Complete of Stitching